FROM ROUTE REVIEW TO REPAIR

See the Finding. Plan the Maintenance.

Turn roadway photos and sampled video frames into visible asset findings, supporting evidence and maintenance reports organized for follow-up.



What TruInspector supports

1. **Pavement and shoulder conditions**
2. **Signs, delineators and markings**
3. **Photo-linked maintenance reports**

From evidence to report

1. Select the state, industry and evaluation type.
2. Upload photos or recorded video.
3. Submit for Ai analysis and review findings.
4. Download a detailed PDF or photo-linked Excel report.

Stay Ahead of Inspections and Keep Control of Your Project.

Ai-assisted observations support professional review. Confirm applicable standards, field conditions, measurements and project requirements.

ILLUSTRATIVE PICTURE REPORT

Extensive interconnected pavement cracking



VISIBLE OBSERVATION

A broad area of interconnected cracking is visible across the wheel path. The pattern suggests advanced surface deterioration and possible loss of support, but imagery alone cannot establish depth, structural capacity or the full affected limits.

RECOMMENDED CORRECTIVE-WORK STEPS

Confirm limits, crack width, rutting, drainage and base support in the field. Remove failed material where required, repair the underlying support, place a compatible pavement repair, restore markings if disturbed and document the completed limits.

POTENTIAL PRODUCTS OR FIXTURES

Approved asphalt repair mix, tack coat, base material, crack treatment where applicable, traffic-control devices and pavement-marking material.

Field verification required. The finding must be reviewed against the selected jurisdiction, applicable requirements, supplied contract documents and actual site conditions.

Illustrative image and finding - not a live inspection, official citation, engineering decision or compliance result.